

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/14/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/10/12 – 0700, 05/17/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Observed RI crew at MP10.0. • Ceresco Dam, Legacy work continued. • MP8.48 boom, no sheen observed. • MP8.5 Boom, no sheen observed. • MP8.75 RDB, boom sheen observed. • MP30.8 Boom, sheen observed. • MP30.8 sandbar, sheen observed to be coming from. • MP30.75 RDB, sheen observed. • Morrow Lake Delta, poling crew observed. • Morrow Lake Delta, sheen sweep boat. • Morrow Lake, sheen sweep boat and poling boats observed out in the lake. • Morrow Lake, poling crew observed in southwestern cove area. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			